


マウスを充電する

Swiftpoint GTを充電するには

1. コンピューターのUSBポートあるいはUSB充電用アクセサリにUSB充電器(兼レシーバー)を差し込みます。
2. マウスをUSB充電器に載せます。

充電中はLEDが点滅し、充電が完了すると消えます。フル充電には最大90分かかります。



マウスを使用するには、底面のスイッチをONにしてください。

USBを使ってマウスを接続する

マウスの接続にUSBを使うには、コンピューターのUSBポートにUSB充電器(兼レシーバー)を差し込み、マウス底面のスイッチをOFFからONにします。マウスは自動でコンピューターに接続されます。

Bluetooth 4.0を使ってマウスを接続する

充電が完了したら、Bluetooth 4.0を使ってコンピューターに接続できます。USB充電器を外し、マウスのスイッチをOFFにしておきます。

Windows 8または8.1の場合 (※Windows 7 はBluetooth 4.0にサポートしません)

1. 画面の右下隅にポインターを合わせ、チャームメニューを表示させます。
2. 「設定」を選択し、「PC設定の変更」を選択します。
3. 次に、

Windows 8では、

「デバイス」を選択し、「デバイスを追加」を選択します。

Windows 8.1では、

「PCとデバイス」を選択し、左の列から「Bluetooth」を選択します。

Bluetoothで接続しているときは、USB充電器(兼レシーバー)は、コンピューターのUSBポートではなく、USB充電用アクセサリに差ししておくことができます。

4. すでにSwiftpoint GTがリストにある場合は、それらを選択してすべて削除してください。
5. マウスのどちらかのボタンを押しながら、底面のスイッチをONにします。LEDが点滅しペアリングモード(検出待ち)になります。
6. 検索結果のリストにSwiftpoint GTが表示されたらクリックします。インストールが行なわれ、コンピューターと接続されます。

その他の機器の場合

まずコンピューターや他の機器で接続の準備を行い、次にSwiftpoint GTをペアリングモード(検出待ち)にします。ペアリングモードにするには、マウスのどちらかのボタンを押したまま底面のスイッチをOFFからONにします。LEDが点滅しペアリングモードになります。

?



6

?



z





To go back in your browser, hold the front button, then click the rear button.


To gesture, tilt the mouse as shown to engage the stylus, then drag the stylus on the mousing surface to swipe and scroll.

To perform edge gestures (Win 8), hold the rear (right-click) button and engage the stylus:

- 1 Drag right to left to bring up Charms.
- 2 Drag left to right to bring up the application switcher. Lift the stylus to launch an application.
- 3 Drag up or down to zoom, depending upon the application being used.



Tilt to gesture



Configuring the Swiftpoint GT (Win 8)

To adjust configuration settings for your Swiftpoint GT:

1. Move the switch on the underside of the mouse to CONFIG.
2. Follow the on-screen instructions.
3. Once configured, slide the switch to ON.

The Gesture Technology Driver accesses more gestures. Extra gestures include:

- 1 Go backward and forward in Internet Explorer with left and right flicks.
- 2 Pan in Microsoft Excel by dragging left and right.
- 3 Pan in Bing maps by dragging.

The Gesture Technology Driver also provides inertia and spring-back behaviours.

To install the driver:

1. Move the switch on the underside of the mouse to CONFIG.
2. Follow the on-screen instructions.